

Horsepower	Year	Spark Plug Number (see notes 1 and 2)	Gap (in.)
88, 90, 100, 110, 112, 115	1979 - 1998	QL77JC4 or QL82C	.030
90, 115 (60° V4 Eagle)	1995 & newer	QL78YC (see note 3)	.030
90, 115 TurboJet (90° crossflow V4)	1994 - 1997	QL77JC4 or QL82C (see note 3)	.030
100	1966	J4C	.030
100	1967 - 1968	L78V Surface Gap or QL77JC4	.030
100	1971 - 1972	L76V Surface Gap or QL77JC4	.030
100 Commercial	1984 - 1998	L78V or QL16V Surface Gap	
105 Jet (60° V6)	1993 & newer	QL78YC (see note 3)	.030
105 Commercial (60° V4)	1997 - 2001	QL78YC (see note 3)	.030
115	1969 - 1970	L76V Surface Gap or QL77JC4	.030
120, 140 (90° V4 Looper)	1985 - 1993	QL77JC4 or QL16V Surface Gap	.030
120, 130, 135, 140 (90° V4 Looper)	1994 - 2001	QL78YC (see note 3)	.030
125	1971 - 1972	L76V Surface Gap or QL77JC4	.030
135, 140	1973 - 1984	UL77V or L16V Surface Gap	
150, 175 (60° V6)	1991 & newer	QL78YC (see note 3)	.030
150 Commercial (60° V6)	1993 - 2001	QL78YC (see note 3)	.030
150, 155 (90° crossflow V6)	1978 - 1987	UL77V or L16V Surface Gap	
150, 175 (90° crossflow V6)	1988 - 1991	QL77JC4 (see note 3)	.030
155 Commercial	1989 - 1992	QL16V Surface Gap	
175, 185	1977 - 1987	UL77V or QL16V Surface Gap	
185 Commercial	1990 - 1993	QL16V Surface Gap or QL77JC4	.030
200	1976 - 1983	UL77V or QL16V Surface Gap	
200, 225	1986 - 1993	QL77JC4	.030
200 Commercial	1992	QL16V or L16V Surface Gap	
200 Commercial	1993 - 2001	QL78YC (see note 3)	.030
200, 225, 225HO	1994 - 2001	QL78YC (see note 3)	.030
235	1978 - 1985	QL16V or UL77V Surface Gap	
250, 275, 300 (V8)	1985 - 1998	QL78YC (see note 3)	.030
OMC Sea-Drive 2.5, 26 Litre	1988 - 1992	UL77V	
3.0 Litre	1988 - 1992	QL77JC4 (see note 3)	.030
OMC Sea-Drive 3.6, 4.0 Litre	1988 - 1992	QL77JC4 (see note 3)	.030
OMC Sail-Drive (Zepher)	1977 - 1984	QL8YC	.045

NOTES:

1. All spark plugs are Champion brand unless otherwise specified.
2. When more than one plug number appears, the first plug listed is the preferred spark plug.
3. On **ALL** VRO/OMS equipped motors the "QL" supressor plug is recommended.

* This chart was assembled with the latest available Parts Catalogs, Service Manuals and Service Bulletins as of the revision date. If any discrepancies are found, please notify the moderator.

Revised: 1/22/2007